HealthCare

CSO Customer Support Operations

HOME

# Field Service Bulletin No. 53

Order No.: DD+DIS083.02E

1 piece U3USD MA1

## ADC Compact

Type 5145 / 100/101/140/200/201/240

| Rating | | | When? | | |
|---|---|---|---|---|---|
| safety relevant | reliability | new function | immediately | next service | as required |
| X | | | | X | |

Please file this document in section 13 of your technical documentation

# Must- Modification "Fuse Board Protection Kit" (CM+9.5146.1711.0)

This modification is a MUST – modification. The Fuse board protection has to be installed on all machines in the field.

**Problem**

Lead markers which have not been removed from the cassette before inserting them into the digitizer, may probably get loose and fall down on the fuse board.

This may cause severe damage in the digitizer

**Reason**

There is an uncovered gap between the input buffer and the cover plate of the power unit.

**Solution**

Install the fuse board protection kit to cover the remaining gap.

Order number: CM+9.5146.1711.0



AGFA